

Cajun™ P550R®/P580/P880/P882 Switch Release Notes v5.2.2

Overview

These release notes support the Cajun switch software version 5.2.2 (v5.2.2) for the Cajun P550R, P580, P880, and P882 switches. Release notes are periodically updated with pertinent information. For detailed information about your product, refer to the basic set of user documentation.

You can download software and access the latest release notes and other documentation at:

http://www.avayanetwork.com/

These release notes cover the following topics:

- New Hardware and Software Features on page 2
- Supported Product Binaries and Boot Codes on page 4
- Queue Classification and Servicing Features on page 4
- Enabling Option 82 for DHCP on page 12
- Enabling Traps for Unknown Source Addresses on page 14
- Enhancements on page 17
- Changed CLI Commands on page 17
- Corrected Problems on page 17
- Known Problems and Workarounds on page 18
- Functional Restrictions on page 28
- Documentation Updates and Corrections on page 33
- Technical Support on page 34

New Hardware and Software Features

Version 5.2.2 provides support for the following new hardware software features.

Hardware

- 80-series, 48-port, 10/100 Ethernet Module with Telco connectors (M8048R-100TC)
- 48-volt power supply for the P580

Software Features

Support for:

- The following Queue Classification and Queue Servicing features:
 - Classification of switch port traffic.
 - Classification of layer 2 tagging.
 - Classification of layer 3 traffic (by means of an access control list).
 - Queue servicing by means of weighted fair queueing (WFQ).

For more information about the Queue Classification and Queue Servicing features that are implemented in this release, see "Queue Classification and Servicing Features" on page 4.

- Port mirroring on 80-series modules in fabric mode 2. This feature makes it possible for you to:
 - Monitor traffic that is received and transmitted from a port.
 - Use of up to four monitor (sink) channels for monitoring traffic.

For more information about the port mirroring on 80-series module feature that is implemented in v5.2.2, see "Queue Classification and Servicing Features" on page 4.

Relay Agent Information option (option 82) for Dynamic Host Configuration Protocol (DHCP). When forwarding client-originated DHCP packets to a DHCP server, the Cajun switch inserts this option, which contains information about the switch. The DHCP server uses this information to authenticate the client.

For information on how to enable option 82, see "Enabling Option 82 for DHCP" on page 12 of this document.

- Enhancement of the MAC Address Lock feature. This feature has been available in all previous releases. If a source MAC address is locked at a port (statically configured), a frame with that source MAC will be filtered if received on any other port on the same VLAN. With the enhancement, the feature immediately generates traps to identify all unknown source addresses. If, after sending a trap for an unknown source, the switch continues to receive traffic from the source, the feature generates a trap every 30 minutes until the traffic stops.
 - * **Note:** You can set the trap timer within a range of 60 to 1800 seconds (default) in one second intervals.

For information on how to enable the MAC Address Lock feature and traps for unknown source addresses, see "Enabling Traps for Unknown Source Addresses" on page 14 of this document.

- Load MIB for the ATM Uplink module, v1.1. This feature makes it possible for you to use SNMP commands to:
 - Upload the startup configuration file of the ATM Uplink module to a TFTP server
 - Download the startup configuration file from a TFTP server to the ATM Uplink module.
 - Download a software image to the ATM Uplink module.

Supported Product Binaries and Boot Codes

Table 1 shows the product binary files and boot codes that are supported by v5.2.2 of the Cajun switch software.

* **Note:** Before downloading and running v5.2.2, remove port mirrors with piggyback ports on 80-series modules.

Table 1. v5.2.2 Product Binary and Boot Files

Type of Switch	Binary File	Boot File
P550R	m5500r_v5.02.02.bin	m550boot_v5.00.01.bin
P580	m8000r_v5.02.02.bin	m8000boot_v5.00.01.bin
P880	m8800_v5.02.02.bin	m880boot_v5.00.01.bin
P882	m8000r_v5.02.02.bin	m8000boot_v5.00.01.bin

* **Note:** The m8000r binary files run the supervisor module on both the P580 and P882 switches. These files replace the m8820_vx.x.x files.

Queue Classification and Servicing Features

Overview

Version v5.2.2 contains Queue Classification and Servicing functionality that you can activate from the switch's CLI. You can configure Queue Classification and Servicing functionality for a module, or for individual ports on a module. The main components of the Queue Classification and Servicing functionality are:

- A hierarchical classification mechanism that classifies incoming traffic
- Priority queues through which the switch forwards classified traffic.

The switch first classifies the traffic and then, based upon the classification of the traffic, stores it in the appropriate priority queue. The switch services the queues according to the WFQ algorithm and assigns queue weights.

Classification of Traffic

You can classify traffic by:

- 802.1p tag priority (default)
- Physical source port
- IP characteristics of the frame (source address, destination address, and so forth)

Frames are classified into eight priorities, or classes, ranging in number from 0 to 7. By default, the switch uses the priority from the 802.1p tag field, if present, to assign a priority to a frame.

You can alternately set each physical port with a priority that ranges from 0 to 7. The switch then replaces the default 802.1p tag priority with the port priority as the priority of the frame.

You can, as a third alternative, set classification to be performed by the IP characteristics of packets, instead of 802.1 tag priority or port priority. To classify frames by their IP characteristics, you set a rule in an access control list (ACL). The rule can set a priority for traffic with a specific IP source address or with a specific combination of IP source address, IP destination address, IP protocol, TCP source port, and TCP destination port.

The priority of a rule in an ACL takes precedence over all other priorities in Queue Classification and Servicing classification. Because of this precedence, the switch determines whether a rule in an ACL exists for an IP frame in the final stage of classification. If a rule does exist, the priority associated with the rule replaces the current priority of the frame.

The switch then forwards the frames to the appropriate priority queue based upon the priority that is assigned to the frames.

WFQ Queue-Servicing Algorithm

You can configure the WFQ service policy. The WFQ policy implemented in the Cajun II Queue Classification and Servicing sub-system is a variation of the textbook WFQ algorithm. In Cajun II WFQ, each queue is assigned a weight increment. The weight increment never varies; however, each queue also maintains an accumulated weight, which is updated after each queue service cycle. Queues are serviced based upon their relative accumulated weights. In each queue service cycle, only the queue with the highest accumulated weight is serviced. If there is a tie, the queue with the highest priority (0 – 7 highest) is serviced first. After each queue service cycle, the accumulated weight for the queue that is serviced is reset to the value of its weight increment, and the accumulated weight for the other queues is increased by their respective weight increments.

When you set a port for WFQ, the switch services priority queues according to their assigned weight. The queue with the highest weight is serviced first.

There are two levels to the WFQ command. The first level specifies the modules/ports to be configured. The second level specifies the queue weights.

Port Mirroring on 80-Series Modules

The port mirroring on 80-series modules that is implemented in v5.2.2 provides the ability for the 80-series modules to monitor traffic that a port transmits and receives. Four channels are provided for monitoring traffic, so you can monitor four different ports or port ranges simultaneously.

* **Note:** Your switch must be in fabric mode 2 to perform 80-series port mirroring.

You can configure port mirroring on 80-series modules by using either the command-line interface (CLI) or the Web Agent.

Configuring Port Mirroring By Using the CLI

Use the following CLI commands to configure port mirroring on 80-series modules. You must be in Global Configuration command mode to enter these commands.

* **Note:** For information on how to enter Global Configuration command mode, see "Accessing/Exiting the Command Modes" in chapter 1 of Cajun P550R/P880/P882 Command Reference Guide.

Setting Up Port Mirroring

To set up port mirroring, use the following CLI command:

>(config)# set port mirror fabric_mode2
source-port <mod-port-range> mirror-port
<mod-port-spec> channel <channel> direction
{tx | rx | both} sampling {always | disable |
periodic} [max-packets=sec <max-packets-sec-value>]

where:

<mod-port-range> is either the single port or the range of ports that you want to mirror.

See Table 2 on page 8 for the specific port ranges that you can mirror.

Table 2. Port Ranges for 80-Series Port Mirroring

Module	Port ranges that you can mirror
4-port gigabit modules	• 1-2
	• 3–4
	• Any single port
	You can mirror any four single ports simultaneously (one port per channel). However you cannot mirror a port range and a single port within that range simultaneously.
	Example: You <i>can</i> mirror port 1 on channel 1, port 2 on channel 2, and port 3 on channel 3 simultaneously. However, you <i>cannot</i> mirror ports 1 through 2 on channel 1 and port 2 on channel 2 simultaneously.
8-port gigabit modules	• 1–4
	• 5–8
	Any single port
	You can mirror any four single ports simultaneously (one port per channel). However you cannot mirror a port range and a single port within that range simultaneously.
	Example: You <i>can</i> mirror port 1 on channel 1, port 2 on channel 2, and port 3 on channel 3 simultaneously. However, you <i>cannot</i> mirror ports 1 through 4 on channel 1 and port 2 on channel 2 simultaneously.

Table 2. Port Ranges for 80-Series Port Mirroring

Module	Port ranges that you can mirror
24-port 10/100 modules	• 1–12 — any 1 port or the entire range.
	• 13–24 — any 1 port or the entire range.
	If you mirror a single port, you can mirror only 1 port per range at a time.
	Example: You <i>can</i> mirror port 1 on channel 1 and port 13 on channel 2 simultaneously. However, you <i>cannot</i> mirror port 1 on channel 1 and port 2 on channel 2 simultaneously.
48-port 10/100 modules	• 1–12 — any 1 port or the entire range.
	• 13–24 — any 1 port or the entire range.
	• 25–36 — any 1 port or the entire range.
	• 36–48 — any 1 port or the entire range.
	If you mirror a single port, you can mirror only 1 port per range at a time.
	Example: You <i>can</i> mirror port 1 on channel 1 and port 13 on channel 2 simultaneously. However, you <i>cannot</i> mirror port 1 on channel 1 and port 2 on channel 2 simultaneously.

- *** Note:** You cannot mirror transmit traffic of multiple source ports to one mirror port.
- <mod-port-spec> is the port to which you want to mirror traffic.

Both the source port and mirror port must either:

Be on the same vlan and have the same vlan binding

or

Have vlan binding set to bind to all

- * **Note:** Avaya recommends that you mirror traffic to a port of the same speed or faster than the source port.
- <channel> is the mirror channel that you want to use (1-4).
- {TX | RX | Both} is the direction of traffic that you want to mirror.
 - * **Note:** You can mirror transmit traffic of only one source port to the mirror port. You cannot mirror transmit traffic of multiple source ports to one mirror port.
- {always | disable | periodic} is how often you want the mirror port to receive traffic samples.
- <max-packets-sec-value> is the maximum number of packets per second that you want the mirror port to receive. (Enter a value for this variable only if you set the sampling to periodic.)

Removing Port Mirroring

To remove port mirroring, use the following CLI command:

>(config)# clear port mirror fabric_mode2
channel <channel>

where <channel> is the mirror channel that you want to remove.

Viewing Information about Port Mirroring

To view information about port mirroring, use the following CLI command:

>(config)# show port mirror fabric_mode2

This command displays the source ports, mirror port, direction being mirrored, sampler type, and maximum packet per second for all port mirrors that are currently set up.

Configuring Port Mirroring By Using the Web Agent

Setting Up Port Mirroring

To use the Web Agent to set up port mirroring:

- 1. Expand the Modules & Ports folder.
- 2. Click Port Mirroring.

The Port Mirroring Information page opens.

- **3.** In the **Source Port** column, select the port that you want to mirror.
- **4.** In the **Mirror Port** column, select the port to which you want to mirror traffic.

Both the source port and mirror port must either:

- Be on the same vlan and have the same vlan binding
 or
- Have vlan binding set to bind to all
- **5.** In the **Direction** column, select the direction of traffic that you want to mirror.
- **6.** In the **Sampler Type** column, select how often you want the mirror port to receive traffic samples.
- **7.** Do one of the following:

IF you select	THEN
Periodic in the Sampler Type column	In the Max Packets per Second column, enter the maximum number of packets per second that you want the mirror port to receive.
Disable or Always in the Sampler Type column	Go to step 8.

8. Click Apply.

Removing Port Mirroring

To use the Web Agent to remove port mirroring:

- 1. Expand the Modules & Ports folder.
- 2. Click Port Mirroring.

The Port Mirroring Information page opens.

- **3.** In the **Source Port** column, select None for the port mirror that you want to remove.
- 4. Click Apply.

Viewing Information about Port Mirroring

To use the Web Agent to view information about port mirroring:

- 1. Expand the Modules & Ports folder.
- 2. Click Port Mirroring.

The Port Mirroring Information page opens. This page displays information about all port mirrors that are setup.

Enabling Option 82 for DHCP

Option 82 for DHCP includes two suboptions:

- Suboption 1 identifies the slot and physical port number from which the DHCP request was received.
- Suboption 2 identifies the IP address and, if available, the system name of the switch.

By default, both of these suboptions are enabled. You can change the status of either or both suboptions by using the Web Agent, Command Line Interface (CLI), or SNMP.

Changing the Status of Option 82 by Using the Web Agent

To use the Web Agent to change the status of option 82:

1. Open the IP Global Configuration page.

For information on how to open this page, see "Enabling IP Routing" in chapter 9 of Cajun P550R/P880/P882 Switch User Guide Version, v5.0.

2. Enable or disable the suboptions as appropriate in the **DHCP**Option - Circuit Info and **DHCP** Option 82 - Agent Info fields.

Changing the Status of Option 82 by Using the CLI

To use the CLI to change the status of option 82, enter Global Configuration mode and use the following commands:

- To enable suboption 1, use the following command:
 - >(config)# ip dhcp circuit-info
- To enable suboption 2, use the following command:
 - >(config)# ip dhcp agent-info
- To disable suboption 1, use the following command:
 - >(config)# no ip dhcp circuit-info
- To disable suboption 2, use the following command:
 - >(config)# no ip dhcp agent-info
- * **Note:** For information on how to enter Global Configuration command mode, see "Accessing/Exiting the Command Modes" in chapter 1 of Cajun P550R/P880/P882 Command Reference Guide.

Changing the Status of Option 82 by Using SNMP

To change the status of option 82 by using SNMP, use the MIB items that are listed in Table 3. These MIB items are defined in **cjnipv4serv.mib**.

Table 3. MIB, MIB Items and OIDs for Option 82

MIB	MIB Item	OID
cjnipv4serv.mib	cjnDHCPOpt82Sub1Enabled	1.3.6.1.4.1.1751.2.43.2.5.5.1
	cjnDHCPOpt82Sub2Enabled	1.3.6.1.4.1.1751.2.43.2.5.5.2

Enabling Traps for Unknown Source Addresses

To enable traps for unknown source addresses, you must first enable the MAC Address Lock feature. You can enable this feature and traps for unknown source addresses by using the Web Agent, CLI, or SNMP.

Enabling MAC Address Lock and Traps by Using the Web Agent

To use the Web Agent to enable the MAC Address Lock feature and traps for unknown source addresses:

1. Manually add the "permitted" MAC addresses to the Address Forwarding Table (AFT).

For information on how to manually add MAC address to the AFT, see "Adding Entries to the AFT Manually" in chapter 6 of Cajun P550R/P880/P882 Switch User Guide, Version v5.0.

- **2.** Enter the following information on the Switch Port Configuration page for the port:
 - **a.** Set the **Allow Learning** field to **Disable**.
 - **b.** Set the **Known Mode** field to **Enable**.

Note: To prevent flooding of frames from unknown source addresses, set the **Known Mode** field to **Enable** for all ports on the same VLAN as the port for which you are enabling MAC address lock.

- **c.** Set the **Intrusion Trap** field to **Enable**.
- **d.** Adjust the trap timer, if desired.

See "Configuring Switch Port Parameters" in chapter 5 of *Cajun P550R/P880/P882 Switch User Guide Version 5.0*, for information on how to perform these procedures.

Enabling MAC Address Lock and Traps by Using the CLI

To use the CLI to enable the MAC Address Lock feature and traps for unknown source addresses:

1. Enter Global Configuration mode.

The CLI displays the > (config) # prompt.

- **2.** Use the following command to manually add the "permitted" MAC addresses to the Address Forwarding Table (AFT):
 - >(config)# set aft entry <mac address> vlan <vlan-id> portbinding forward <mod-port-spec>
- **3.** Use the following command to disable learning on a port or port range:
 - >(config)# set port allow-learning <modswport-range> disable
- **4.** Use the following command to enable known-mode on a port or port range:
 - >(config)# set port known-mode <mod-swport-range> enable
 - * Note: To prevent any flooding of frames from unknown source addresses, enter all ports on the same VLAN as the port for which you are enabling MAC address lock
- **5.** Use the following command to enable intrusion traps on a port or port range:
 - >(config)# set port intrusion-trap <mod-swport-range> enable
- **6.** Use the following command to set the intrusion trap timer to other than the default setting:
 - >(config)# set port intrusion-trap-timer <mod-swport-range> <intrusion-trap-timer-value>

Enabling MAC Address Lock and Traps by Using SNMP

The MIB items that you use to perform this procedure are located in **ProminetMib.txt**, version 5.2.

To use SNMP to enable the MAC Address Lock feature and traps for unknown source addresses:

1. Use the MIB items that are listed in Table 4 to manually add the "permitted" MAC addresses to the AFT.

Table 4. MIB, MIB Items, and OIDs for MAC Address Lock

MIB	MIB Item	OID
ProminetMib.txt, version 5.2	promL2AddressControlIndex	1.3.6.1.4.1.2167.5.1.4.3.1.1
	promL2AddressControlMacAddress	1.3.6.1.4.1.2167.5.1.4.3.1.2
	promL2AddressControlPortBinding	1.3.6.1.4.1.2167.5.1.4.3.1.3
	promL2AddressControlVlanID	1.3.6.1.4.1.2167.5.1.4.3.1.4
	promL2AddressControlPriority	1.3.6.1.4.1.2167.5.1.4.3.1.5
	promL2AddressControlPersistence	1.3.6.1.4.1.2167.5.1.4.3.1.6

2. Use the MIB item that is listed in Table 5 to disable learning on a port.

Table 5. MIB, MIB item, and OID for Disabling Learning

MIB	MIB Item	OID
ProminetMib.txt, version 5.2	promSwitchPortLearningMode	1.3.6.1.4.1.2167.5.2.1.1.4

3. Use the MIB item that is listed in Table 6 to enable known mode on a port.

Table 6. MIB, MIB item, and OID for Enabling Known Mode

MIB	MIB Item	OID
ProminetMib.txt, version 5.2	promSwitchPortKnownMode	1.3.6.1.4.1.2167.5.2.1.1.7

4. Use the MIB item that is listed in Table 7 to enable intrusion traps on a port.

Table 7. MIB, MIB Items, and OIDs for MAC Address Lock and Traps

MIB	MIB Item	OID
ProminetMib.txt, version 5.2	promSwitchPortIntrusionTrap	1.3.6.1.4.1.2167.5.2.1.1.19

Enhancements

The following events are now logged in the event log:

- Saving the running configuration to the startup configuration
- Creating an IP interface
- Modifying an IP interface
- Deleting an IP interface

Changed CLI Commands

- The get Fabric_mode command replaces the get Cajun_mode command.
- The set Fabric_mode command replaces the set Cajun_mode command.

Corrected Problems

The following problems have been corrected in this release:

- Pulling the base port on a hunt group no longer causes traffic to lose duplexity and broadcast to all ports within the VLAN.
- The SNMP error message no longer displays when you perform a LOADMIB operation.
- You can now create a row in the GenAppFile table in the LOAD MIB.
- A software modification has been implemented for the LEDS on the 24-port, 10/100 Ethernet module with RJ45 connectors. The LEDs no longer illuminate when nothing is connected to them.
- The switch no longer stops learning remote MAC addresses over the ATM link when 36 or more virtual switch ports (VSPs) are configured.
- When running AppleTalk Network Assistance, the switch no longer stops forwarding layer 3 traffic.

Known Problems and Workarounds

The following known problems and workarounds apply to Cajun P550R, P580, P880, and P882 switches that are running switch software, v5.2.2. If a known problem has a viable workaround, it immediately follows the Problem statement. If the known problem has no viable workaround, it is listed as a bulleted statement.

ARP

Problem: 50-Series and 80-Series modules lose ARPs after you perform an

initialization of NVRAM (NVRAM init).

Workaround: Reboot the switch twice after performing an NVRAM init.

ATM Uplink Modules

The following problem has no workaround:

■ The 50-series ATM Uplink modules do not work in slot 16 or slot 17 if you are using an 80-Series Supervisor module in a Cajun P882 switch.

Command Line Interface (CLI)

The following problem has no workaround

- The "!" character, when used as part of a CLI command, is considered a comment by the Cajun switch software:
 - If you type "!" BEFORE a CLI command, the switch ignores the command and returns you to the CLI prompt.
 - If you type "!" after a CLI command, the switch displays an Invalid Command or Syntax Error error message.

Flood Rate Limiting

Problem: The options for setting flood rate limiting on 80-series, 10/100

Ethernet modules and on 80-series, 100 Base-FX Ethernet modules are incorrect. The correct rates are not available from the Web Agent

or CLI.

Workaround:

Use the following table to determine the option that corresponds to the rate that you want to set.

Table 8. Flood Rate Limiting on 80-Series 10/100 Modules

Desired Rate	Web or CLI Setting
80%	10%
40%	5%
20%	2%
10%	1%

* Note: Do not use the 20%, 40%, or 80% options of the Web Agent or CLI.

Frames Transmitted with Cyclic Redundancy Check (CRC) Errors

Problem:

For certain revisions of the Cajun P550R/P580/P880/P882 switch 12- and 20-port module (Model M5520-100TX, module Type 9, revision level A or B and M5512-100TX, Revision A), a temperature sensitivity problem has been found when operating at 10 Mbps. This sensitivity results in the port transmitting frames with CRC errors. These frames, since they have CRC errors, are then dropped by the receiving station.

Workaround:

The following **legacy-cli** command allows you to implement a new configuration to disable the power saving mode of the Phy chip. This has the same effect as moving the port's operational temperature past the problem range. The new configuration is saved only in NVRAM:

> port set DisablePowerSave <port> on

* **Note:** Except for this command, the Legacy-CLI is not supported by the Cajun Switch.

Hot Swap Modules

The following problems have no workaround:

- Hot swapping 50-series modules may cause SEPROM and SMAC panic messages to appear in the event log. These messages are for informational purposes only and should be ignored.
- When you insert a module into the switch, traffic may be affected for up to seven seconds while the module performs its hardware diagnostics.

IGMP Group Membership Table

Problem: The IGMP Group Membership Table does not display all members

when viewed from the Web Agent if the members are on different

interfaces.

Workaround: Use the following CLI command in User mode to view the members

of IGMP groups:

> show ip igmp groups

Intelligent Multicasting

The following problem has no workaround:

■ Layer 2 Multicast data is not forwarded on slot 17 in the P882 chassis.

Problem:

Intelligent Multicasting can block protocols to non-multicast routers. If you have enabled Intelligent Multicasting and have configured a VLAN to one or more non-multicast routers or multicast-capable endstations, Intelligent Multicasting configures router ports where multicast-enabled routers reside. These multicast router ports allow all multicast packets to the adjacent multicast routers. Ports connected to non-multicast enabled routers are not considered router ports and do not receive multicast traffic. The problem can arise when multiple IP multicast addresses are mapped to the same multicast MAC address, resulting in protocol packets not being sent to the adjacent non-multicast enabled routers.

Example:

The unicast routing protocol in use on all connected routers is OSPF, and all ports are on the same VLAN. An endstation joins the IP multicast group 226.128.0.5 on port 1. The MAC address for the group is 01:00:5E:00:00:05. IGMP snooping creates a session for this MAC address, with port 1 as the client port. There is a non-multicast OSPF router attached to port 2. OSPF uses the IP multicast link scoped group 224.0.0.5, which also maps to a MAC address of 01:00:5E:00:00:05. Because port 2 is not considered a router port, and it is not part of the 01:00:5E:00:00:05 session, the switch only passes OSPF messages out port 1. Other protocols, such as the Service Location Protocol (RFC 2608), use 224.0.1.22 and 224.0.1.35, which can be blocked by endstations joining sessions that map to the same MAC address.

Note: This is the same problem that is discussed in the Microsoft Product Support Article Q223136 that can be found at:

http://support.microsoft.com/support/kb/articles/Q223/1/ 36.asp

involving RRAS setup. This specific issue, however, should not break routing protocols as suggested in this article because the Cajun switch ignores joins for local multicast groups (224.0.0.x).

Workaround:

Check that all ports that are connected to the router are configured as router ports. This prevents all router-to-router messages from being blocked.

If other non-router protocols, such as the Server Location Service, are in use, create static sessions as needed. Do not create static sessions that conflict with the protocols used on your network.

Refer to the following web site for a complete list of internet multicast addresses recognized by the IANA:

http://www.isi.edu/in-notes/iana/assignments/ multicast-addresses

Note: Enable is the default state for "Rate Limiting" on 10/100 Mbps ports. Multicast traffic and broadcast traffic is rate-limited (to 20%) on 10/100 Mbps ports.

Multicast traffic is rate-limited unless Intelligent Multicasting is enabled. Multicast traffic for which the Intelligent Multicast session was created is not subject to rate limiting unless the rate limiting state is set to Enable (all multicasts included). If you do not want to enable rate limiting of multicast traffic on a port, either:

Disable Intelligent Multicasting

or

■ Disable Rate-limiting on the port.

IP

The following problems have no workaround:

- If you create overlapping IP interfaces (interfaces in the same subnet), the state of the second interface is INACTIVE.
- If you enter a non-numeric value in either the Network Address or Mask fields on the IP Static Route page, all of the numbers are rejected and the field converts back to 0.

IPX

Problem:

802.3 IPX routed frames are sometimes padded in such a way that they are incompatible and discarded by older IPX clients and drivers.

Workaround:

Use newer client software (v2.5 or later) or use a frame format other than 802.3 (Avaya recommends that you use format 802.2). If you cannot use new client software or a newer frame format, use the following CLI commands to allow 802.3 IPX clients to connect:

- ■IPX Forward Set
- ■IPX Forward Get

Refer to the *Cajun P550R/P880/P882 Switch Command Line Reference* guide for more details about these new commands.

L3 Forwarding Cache

Problem:

Attempting to change the maximum number of entries in the L3 Forwarding Cache while you are using a licensed 80-Series module will cause the switch to stop responding, if the switch is configured with 10,000 entries or more. The CLI or the Web interface will not respond and the scrolling text on the supervisor will stop.

Workaround:

Flush the L3 Forwarding Table before changing the L3 Forwarding Cache Max Entries value.

Option 82 for DCHP

The following problems have no workarounds:

- The switch does not add relay agent information (option 82) to a BOOTP request.
- The option 82 relay agent does not check frames for the IPSEC authentication header or IPSEC encapsulating security payload.

PCMCIA

The following problem has no workaround:

• Text files copied from the PCMCIA card cannot be read.

Problem:

The 80-Series Supervisor module will not fully reset if you initiate a reset from either the CLI or the web agent after you perform a command that involves reading from, or writing to, the PCMCIA card.

Workaround:

Power the switch off and then on after you read from or write to the PCMCIA card.

Point-to-Point Protocol (PPP) and Telnet

The following problems have no workaround:

- A Telnet session to the serial port via PPP may time out during attempts to transfer large files, such as executable images, to a Trivial File Transfer Protocol (TFTP) server. This does not terminate the file transfer. An in-progress TFTP file transfer ends only after the file transfer is completed.
- A new baud rate may take effect before the current PPP connection is terminated if the baud rate change command is entered more than once. This results in the termination of the PPP connection. This requires re-establishment of a PPP connection.

Port Mirroring

80-Series Modules

The following problem has no workaround:

• Removing a port mirror causes an interface to stay in the "UP" state with no connections to the interface.

Problem:

If you mirror multiple ports, the switch monitors both transmit and receive traffic regardless of the direction of traffic that you specify. The switch continues to monitor both directions of traffic even if you remove the port mirror with multiple source ports and set up a new port mirror with a single source port.

Workaround:

Reset the switch before setting up a port mirror with a single source port.

Problem:

Version 5.2.2 of the switch software does not support piggyback ports on 80-series modules. If your switch is running a version earlier than 5.2.2 and you set up a port mirror with a piggyback port on an 80-series module and you then download 5.2.2, specify 5.2.2 as the startup configuration, and reset the switch, the switch retains the port mirroring information and will reset repeatedly as long as the port mirror exists.

Workaround:

Before downloading and running v5.2.2, remove port mirrors with piggyback ports on 80-series modules.

50-Series Modules

The following problems have no workaround:

- When you try to mirror a blocked port, the Web Agent displays the port as forwarding, but it is blocked. When you remove the blocked port from being mirrored, you receive panic messages on the console. The problem does not interrupt traffic or cause any other problems in the network.
- If a standby supervisor module installed in slot 2 has become the Active supervisor (CPU) due to a failover, the web agent shows the supervisor module in slot 1 as available for mirroring during a port mirroring operation. This is incorrect. This problem does not affect traffic running in the network.

* **Note:** The Supervisor module should not be configured for port mirroring even if it displays as available for port mirroring.

■ If a router port for intelligent multicasting is mirrored with a piggyback port, the piggyback port is listed instead of the router port.

Redundant Switch Controller

The following problem has no workaround:

- Do not enable redundancy unless you have a redundant switch controller.
- On a P880 with an 80-series supervisor module, the redundant switch controller may not take over when the active switch controller fails.

Remote Monitoring (RMON)

The following problems have no workaround:

- 30 minute RMON statistics always show utilization as 0 (Zero) on a heavily used Gigabit Ethernet port.
- Statistics for unicast frames do not work when using multilayer (ISL) tagging.

Simple Network-Management Protocol (SNMP)

The following problems have no workaround:

- Cold start traps cannot be transmitted out of inband interfaces after you enable Spanning Tree.
- ipAddrTable does not display inactive interfaces (VLANs). An inactive interface occurs when there are no active ports on a VLAN.

Problem:

- If you use the CLI to perform either of the following commands, the supervisor module stops responding and resets:
 - snmp walk aarpNetAddress
 - snmp walk cjnAtEchoSend

Workaround: Use SNMP from a management station to access these MIB items.

Problem: If you remove the Public community string from the SNMP

Community Management, save the running config to the startup config and then reset the switch, the Public community string you

removed is not deleted.

Workaround: Change the Public Community string to a different name.

P580/P882 Chassis Slot 2

The following problem has no workaround:

 Cajun P580/P882 switches running in Fabric 2 mode will not route inbound multicast traffic received by an unlicensed 80-Series module when installed in slot 2.

Downloading the Startup Configuration File

Problem: Downloading the startup configuration file produces panic messages

in the CLI of the supervisor module and ATM Uplink module.

Workaround: Ignore these messages.

Supervisor Module

80-Series Supervisor Module

The following problem has no workaround:

■ To successfully synchronize two 80-Series Supervisor modules (M8000R-SUP), both modules must be in 48-port

mode and in the same fabric mode.

Problem: Panic messages display on the CLI and on the Primary Supervisor

LED readout after you install a second Supervisor module for

redundancy.

Workaround: Ignore these messages.

Problem:

When the 80-series Supervisor module boots, the switch displays the following error message in the CLI:

Undefined Error -- FILE:gqswport.cLINE:449 Value Oxffffffc: Error changing the GQ 'port use diffserv' flag

Workaround:

Ignore this message.

50-Series Supervisor Module

The following problem has no workaround:

■ The display on the P880 switch M5500R-SUPA supervisor module may not initialize properly. However, if it becomes the active supervisor module, the display becomes functional and displays the proper information.

Switch Ports

The following problem has no workaround:

■ While switch port parameters are reflected across all ports of a Hunt group, spanning tree parameters are not. If you change the spanning tree priority of the flood port of a Hunt group, but that port does not come up first when bringing up the Hunt group, the spanning tree priority for the group reverts to the default.

Problem:

If a switch port is moved from Bind to Receive to Static, all previously bound VLANs are not removed.

* Note: This is NOT a problem with the **Bind to All** setting.

Workaround:

Remove VLANs manually from a port when changing a switch port connection from Bind to Receive to Static.

RIP

Problem: Configuring a RIP V1/V2 interface sends V2 packets to a V1

interface.

Workaround: If the corresponding interface is in RIP v1, configure your interface

to RIP v1.

VLAN Issues

The following problem has no workaround:

■ If you want a port to use both the VLAN auto-learning feature and VLAN binding type of **Bind to Received** or **Bind to All**, make sure that you set the VLAN binding type *before* you set Auto-learn to **Enable** or else the port may not be automatically added to the VLAN.

Web AFT Issues

Problem: The Web Address Forwarding Table (AFT) search does not return all

entries that meet your search criteria when you search by status of

entries.

Workaround: Use the CLI to search the AFT by the status of entries.

Functional Restrictions

This section provides the functional restrictions for version 5.2.2 of the switch software.

Auto-Negotiation

- M5520-TX (P/N M5520-100TX) boards manufactured with a Quality Phy do not auto-negotiate with Xircom brand adapter cards. If you are having this problem, disable autonegotiation on the affected ports, and set the port speed and duplex state manually.
- Auto-negotiation should be disabled only on 50-series modules that have remote fault detection enabled.

Problem: You may experience difficulties with auto-negotiation between

some releases of the 10/100Base-TX Module (M5510-100TX, M5520-100TX, M5510R-100TX, M5512R-100TX) and adapter cards using physical interfaces manufactured by National Semiconductor.

The symptom is loss of connectivity.

Workaround: Either:

■ Disable auto-negotiation

■ Use a patch cable that is longer that 5 meters

■ Enter the following Enhanced CLI command in legacy mode:

> port set NationalPhyMode <slot>.<port> enable

The factory default for the National Phy Mode is Enable.

Checksum Error Message

Problem: The following checksum error displays after you upgrade from 4.3.x

code to v5.x code:

Bad file header compressed checksum...transfer cancelled.

Workaround: Ignore the checksum error and reboot the switch to upgrade the

software.

CajunView v3.0

CajunView v3.0 does not support 80-series hardware. CajunView v4.0 will support 50-series hardware and 80-series hardware on

Cajun switch software code version 5.1 and later.

CPU Synchronization

Problem: If you attempt to synchronize the active supervisor and redundant

supervisor while the supervisor is being heavily used, TFTP transfers from the active supervisor to the redundant supervisor may time out

and fail.

Workaround: Repeat the synchronization when use of the supervisor has

decreased.

Legacy CLI

Problem: The Legacy CLI setup command does not save information that you

enter.

Workaround:

The Legacy CLI is no longer supported in this release except for the following command that allows you to implement a new configuration to disable the power saving mode of the Phy chip (refer to the *Frames Transmitted with Cyclic Redundancy Check (CRC) Errors* section on page 3 under Known Problems and Workarounds:

> port set DisablePowerSave <port> on

Distance Vector Multicast Routing Protocol (DVMRP)

The switch may lose a small number of DVMRP neighbor-toneighbor probe messages which may cause multicast routing instability under heavy loads.

IEEE 802.1Q Packets

Problem:

When a tagged IEEE 802.1Q packet arrives on a port that is set to "bind-to-all" and the VLAN does not exist on the switch, the packet is forwarded to that port's default VLAN.

Workaround:

To prevent unintended forwarding of unknown VLAN traffic to the port's default VLAN, configure the port default VLAN to "discard".

* Note: Automatic VLAN creation does not work if the port default VLAN is "discard", because the switch does not learn this VLAN.

Hunt Groups

- Hunt groups can only consist of all layer 2 or all layer 3 modules. Hunt groups do not support a mixture of layer 2 and layer 3 modules.
- When 48-port mode is enabled on the switch, you can configure a maximum of thirteen hunt groups on the switch.

Link Status

When a large number of VLANs or endstations are on a hunt group, it may take several seconds for the link status LED to change upon failure.

Loopback Tests

Loopback tests on ports may fail when traffic is present on the link at start-up.

Netscape 6.0

Do not use Netscape 6.0 as a browser with the Cajun Switch Web Agent.

Oversized Packets

Oversized packets are not counted in itemized statistics if the packet size is between 1519 and 1548 bytes.

PCMCIA

Only PCMCIA memory cards purchased from Avaya Inc. are supported in the PCMCIA slot of the M800R-SUP supervisor module.

Port Mirroring

- When using 80-series port mirroring, you cannot mirror transmit traffic of multiple source ports to one mirror port.
- When you use 80-series port mirroring, both the source port and mirror port must either:
 - Be on the same vlan and have the same vlan binding

or

- Have vlan binding set to bind to all
- Your switch must be in fabric mode 2 to perform 80-series port mirroring.
- If you use port mirroring, the port **Frame Tag** field on the Switch Port Configuration page must be set to Use frames (default).

Redundant Controller Support

In the event that a Layer 3 redundant switch controller or element fails, the switch resets itself and records an entry of the event in the event log.

SNMP

To disable SNMP, you must set the access for all community strings to **None**. You cannot disable SNMP by deleting all community strings because the public community string is restored when you reboot the switch.

Software License Keying

Field upgradeable software features, such as routing, are supported only by v5.1.0 and later.

Spanning Tree Protocol (STP)

- In release 4.1 and later, the STP Port Priority range has been changed. The values are now 1 to 15. If you changed the default range in an earlier release, you should verify that the priority is within the allowed range.
- When the STP mode is set to IEEE 802.1D, Bridge Protocol Data Units (BPDUs) are sent out ports that are configured as Clear (non-trunked) even if the port is configured as a trunk (3Com, IEEE 802.1Q, or Dual-Layer) port. To alleviate this problem, disable STP for that port.

3Com Tagging

3Com tagging is not supported for this release.

TFTP File Naming Standard for Embedded NVRAM File System

* Note: All NVRAM files must use an 8.3 format for file names.

When downloading code to the NVRAM file system, use standard 8.3 file naming conventions.

TFTP Download Status Delay

It takes a few seconds before the **Status** button on the TFTP Download screen returns accurate information.

VLAN Issues

- Automatic VLAN creation on P880 50-series supervisor module (M5500R-SUPA) does not work if the port default VLAN is set to "discard". The switch does not learn VLANs with this setting.
- Automatic VLAN creation on an 80-series supervisor module (M8000R-SUP) does work if the port default VLAN is set to "discard".
- If you set a port's VLAN trunking mode to Clear, you must set the VLAN Binding Type to Static (default).
- You may receive an error message stating that the VLAN name is already in use after you add a VLAN and refresh your browser.

Web Agent

Problem:

If you click the Back button after you change a variable from the "Switch Port Config" screen, the variable will change back to the previous setting and the switch will reset. If you change a number of variables and click the Back button, the last variable will change back to the original value and the switch will reset.

Workaround:

This only happens on Microsoft Internet Explorer, version 5.00.2919.6307. Use a later version of Microsoft Internet Explorer.

Documentation Updates and Corrections

The following problems were found in the Cajun P550R/P880/P882 Switch documentation for release v5.0 and will be fixed in release v6.0.

Cajun P550R/P880/P882 Switch User Guide

The following problem was found in the Cajun P550R/P880/P882 Switch User Guide for release v5.0 and will be fixed in release v6.0.

The steps in "Modifying OSPF Interfaces" of chapter 11, "Configuring the OSPF Routing Protocol" should read as follows:

- **1.** Administratively disable the interface on which you want to modify OSPF.
 - * **Note:** You must disable the interface to perform any OSPF modifications to the interface.
- 2. In the navigation pane of the Web Agent window, expand the Routing > IP > OSPF folders.
- 3. Click Interfaces.

The OSPF Interfaces page opens (Figure 11-4).

- **4.** Modify the OSPF interface parameters. Refer to Table 11-3 for an explanation of these parameters.
- **5.** Administratively enable the modified interface.
 - * **Note:** You must reenable the interface for the switch to accept the modifications.

Technical Support

To contact Avaya's technical support:

- * Note: These are new phone numbers as of October 1, 2000.
- From the United States:

1-800-237-0016

From North America:

1-800-242-2121

Outside North America:

Contact your distributor



Appendix A: CLI Commands for Queue Classification and Servicing

Overview

This appendix contains the CLI commands that you use to configure the Queue Classification and Queue Servicing functionality in Version 5.2 of the Cajun switch software. CLI commands exist for the following tasks:

- "Setting the Priority of a Port" on page A-1
- "Setting a Port to Ignore Tag Priority" on page A-2
- "Displaying the Port Settings" on page A-3
- "Setting a Rule in an Access Control List" on page A-4
- "Displaying Access Control Lists" on page A-6
- "Setting WFQ" on page A-7
- "Displaying the Queue Service Settings" on page A-9

Setting the Priority of a Port

Command

Use the set port priority command to set the priority of a port. The syntax of the command is:

set port default-priority {<slot>|<slot-swportrange>}[...,{<slot-num>|<slot-swport-range>}]
<pri>range>}

^{*} **Note:** In this release, you can configure the Queue Classification and Queue Servicing features only by using the CLI. The features are not available in the Web Agent or SNMP.

where

<slot> is the slot number. If you specify this parameter, then all
ports on the module in slot <slot> are set the same way.

<slot-swport-range> is a slot and port range in the form of 3/1 or
3/1-5. If you specify this parameter, then only the ports <swport-range> on the module in slot <slot> are set.

<priority> is the priority that you want to assign to the port. Enter a
number between 0 and 7. The highest priority is 7.

Examples

■ To set the port priority to 0 for all ports on the module in slot 3, enter:

```
set port default-priority 3 0
```

■ To set the port priority to 5 for ports 1 through 5 on the module in slot 3, enter:

```
set port default-priority 3/1-5 5
```

■ To set the port priority to 2 for ports 1 through 5 on the module in slot 3 and for port 1 on the module in slot 6, enter:

```
set port default-priority 3/1-5,6/1 2
```

Setting a Port to Ignore Tag Priority

Command

Use the set port ignore-tag priority command to set a port to ignore the 802.1p tag priority. The syntax of the command is:

```
set port ignore-tag-priority {<slot>|<slot-swport-
range>}[...,{<slot>|<slot-swport-range>}] {on|off}
```

where

<slot> is the slot number. If you specify this parameter, then all
ports on the module in slot <slot> are set the same way.

<slot-swport-range> is a slot and port range in the form of 3/1
or 3/1-5. If you specify this parameter, then only ports <swport-range> on the module in slot <slot> are set.

{on|off} indicates whether you want the port to ignore tag priority. Enter on for the port to ignore the tag priority.

Examples

■ To set all ports on the module in slot 3 to ignore the 802.1p tag priority, enter:

```
set port ignore-tag-priority 3 on
```

■ To set ports 1 through 5 on the module in slot 3 to *not* ignore the 802.1p tag priority, enter:

```
set port ignore-tag-priority 3/1-5 off
```

■ To set ports 1 through 5 on the module in slot 3 and port 1 on the module in slot 6 to ignore the 802.1p tag priority, enter:

```
set port ignore-tag-priority 3/1-5,6/1 on
```

Displaying the Port Settings

Command

Use the show port command to display the settings of a port. The syntax of the command is:

```
show port [{<slot>|<slot-swport-range>}
[...,{<slot>|<slot-swport-range>}]]
```

where

<slot> is the slot number. If you specify this parameter, then the
settings of all the ports on the module in slot <slot> are displayed.

<slot-swport-range> is a slot and port range in the form of 3/1
or 3/1-5. If you specify this parameter, then settings for only the
ports <swport-range> on the module in slot <slot> are displayed.

Examples

To display the settings of all of the ports on the module in slot 3, enter:

```
show port 3
```

■ To display the settings of ports 1 through 5 on the module in slot 3, enter:

```
show port 3/1-5
```

■ To display the settings of ports 1 through 5 on the module in slot 3 and of port 1 on the module in slot 6, enter:

```
show port 3/1-5,6/1
```

Setting a Rule in an Access Control List

Command

Use the access list command to set a rule on an access control list. The rule that you set will be applied on all of the ports on the switch. The command syntax is:

* **Note:** You must enable the access control list on which you want to set a rule. Only one access control list can be enabled at a time.

```
> configure)# access-list <access-list-name>
<access-list-index>
{permit|deny|fwd1|fwd2|fwd3|fwd4|fwd5|fwd6|fwd7|
fwd8} <protocol-id> {<source-ip-addr> <source-
wildcard>|any|host <source-ip-addr>}
[{lt|eq|gt|range} <port> [<port>]] {<dest-ip-addr>
<dest-wildcard>|any|host <dest-ip-addr>}
[{lt|eq|gt|range} <port> [<port>]] [established]
```

where:

<access-list-name> is a unique name that identifies the access control list.

<access-list-index> is the rule number within the access list.

{permit | deny | fwd1 | fwd2 | fwd3 | fwd4 | fwd5 | fwd6 | fwd7 | fwd8} is the priority that you want to set. The number following the fwd option specifies the priority.

In other words, {permit | deny} are not valid selections. The fwdx arguments are "1" based, while the queue priorities are "0" based. Consequently, the "1" based priorities are converted to "0" based priorities by the Queue Classification and Queue Servicing features.

For example, to specify a priority of 0, enter fwd1. You must enter a value for this argument. You cannot omit a fwdx argument from the access-list command.

col-id> is the ID of the protocol to which you want to
assign a priority. RFC791 defines the protocol IDs.

<source-ip-addr> is the source IP address to which you want to
assign a priority.

<source-wildcard> is the inverse of a network mask.

any indicates a source and source-wildcard of 0.0.0.0.255.255. 255.255

host <source-ip-addr> is the IP address of the host for the access list. The source ip address range is 0 to 255.

[{lt|eq|gt|range} <port> [<port>]] is a range of source ports that pass between two hosts or switches using the Transmission Control Protocol (TCP) or the User Datagram Protocol (UDP).

<dest-ip-addr> is the destination IP to which you want to assign
a priority.

<dest-wildcard> is the inverse of a network mask.

any indicates a destination and destination-wildcard of 0.0.0.0.255.255.255.255

host <dest-ip-addr> is the destination IP address of the host. The destination IP address range is 0 to 255.

[{lt|eq|gt|range} <port> [<port>]] is a range of destination ports that pass data between two hosts or switches using the Transmission Control Protocol (TCP) or the User Datagram Protocol (UDP).

[established] permits TCP connections to be established that match the rule.

* Note: You can also configure access control lists by using the Web Agent. For information on how to use the Web Agent to perform this task, see "Creating Standard Access Rules" and "Creating Extended Access Rules" in Chapter 9 of Cajun P550R/P880/P882 Switch User Guide, Version 5.0.

Examples

■ To assign all traffic whose source IP address is 192.188.10.1 a priority of 0, enter:

```
access-list MyAccessList 1 fwd1 192.188.10.1
```

■ To assign all traffic whose source IP address is 192.188.10.2 a priority of 1, enter:

```
access-list MyAccessList 2 fwd2 192.188.10.2
```

■ To assign all traffic whose source IP address is 192.188.10.3 a priority of 2, enter:

```
access-list MyAccessList 3 fwd3 192.188.10.3
```

Displaying Access Control Lists

Use the show access-lists command to display one or more access control lists. The correct command syntax is:

> (configure)# show access-lists [<access-listname>]

where:

[<access-list-name>] specifies the name of the access control list that you want to view. If you do not specify a access control list, the switch displays all of the access control lists.

Setting WFQ

Overview

Setting the weighted fair queuing (WFQ) service policy involves two commands. In the first command, you specify the queue policy, the modules and ports for which you want to set the policy, and whether you want to set the queue service policy for ingress traffic, egress traffic, or both. In the second command, you specify the queue weights.

Command 1

The correct syntax for Command 1 is:

```
> (configure)# set queue-service {<slot>|<slot-
swport-range>}[...,{<slot>|<mod-port-range>}] wfq
egress
```

where:

<slot> is the slot number.

<slot-swport-range> is a slot and port range in the form of 3/1
or 3/1-5. If you specify this parameter, then only the ports
<swport-range> on the module in slot <slot> are set.

egress is the direction of traffic for which the policy is set.

Command 2

The correct syntax for Command 2 is:

```
> queue <queue> weight <weight>
```

where

<queue> is the queue number, which can range from 0 to 7.

<weight> is the weight that you want to assign to the queue.
Weights can range from 0 to 255.

Examples

- To set WFQ for egress traffic on ports 1 through 4 on the module in slot 3, enter:
 - > (configure)# set queue-service 3/1-4 wfq
 egress
- To assign a weight of 1 to queue 0, enter:
 - > queue 0 weight 1
- To assign a weight of 2 to queue 1, enter:
 - > queue 1 weight 2
- To assign a weight of 3 to queue 2, enter:
 - > queue 2 weight 3
- To assign a weight of 4 to queue 3, enter:
 - > queue 3 weight 4

- To assign a weight of 5 to queue 4, enter:
 - > queue 4 weight 5
- To assign a weight of 6 to queue 5, enter:
 - > queue 5 weight 6
- To assign a weight of 7 to queue 6, enter:
 - > queue 6 weight 7
- To assign a weight of 8 to queue 7, enter:
 - > queue 7 weight 8

Displaying the Queue Service Settings

Command

Use the show queue-service command to display the settings for queue service. The correct syntax for this command is:

```
> show queue-service {<slot>|<mod-port-range>}
[..., {<slot>|<mod-port-range>}]
```

where

<slot> is a slot number

```
<mod-port-range> is 0-7
```

If you specify this parameter, then the settings for all of the ports on the module in slot <slot> are displayed.

<slot-swport-range> is a slot and port range in the form of 3/1
or 3/1-5. If you specify this parameter, then the queue service
settings for ports <swport-range> on the module in slot <slot>
are displayed.

Examples

To display the queue service settings for port 1 on the module in slot 3, enter:

> show queue-service 3/1